Friday, 3/24/2006 8:34:12 AM

User:

Linda Lacelle

## **Process Sheet**

Customer

: CC-DAR01 Dart Aerospace Ltd.

**Drawing Name** 

: D1005

**Job Number** 

: 26375

**Estimate Number** 

: 10804

P.O. Number

Prsht Rev.

First Issue

**Previous Run** 

A) U:

This Issue

: 3/24/2006

: NC

: 3/24/2006

: 00015

S.O. No. : NA

**Part Number Drawing Number**  : Z\_CUSTOM : RTN 461

**Project Number** 

: NA

**Drawing Revision** 

: NIA

Material

:IVIA

**Due Date** 

: 3/31/2006

Qty:

Um: Each

Written By **Checked & Approved By** 

Comment

**Additional Product** 

Job Number:



Seq. #:

**Machine Or Operation:** 

Description:

1.0 QC5 INSPECT WORK TO CURRENT STEP



Comment: INSPECT RTN 461 2.0

SMALL FAB 1

SMALL & MEDIUM FAB RESOURCE 1.



Comment: SMALL & MEDIUM FAB RESOURCE 1

REMOVE LABELS AND DISCARD/DISASSEMBLE HARDWARE

06:03:27

3.0

POWDER COATING

POWDER COATING





RE-POWDER COAT PER RS1004, QS005 (4.3.5.1)

4.0

INSPECT POWDER COAT/CHEMICAL CONVERSION



Comment: INSPECT POWDER COAT/CHEMICAL CONVERSION

5.0

SMALL FAB 1

QC3

SMALL & MEDIUM FAB RESOURCE 1





Comment: SMALL & MEDIUM FAB RESOURCE 1 RE-ASSEMBLE PER DRWG D1005 TRACK ANY NEW HARDWARE /B/N'S

	ı
	:
	į
	į
	:
	:
	:

Date: User:

Friday, 3/24/2006 8:34:12 AM

Linda Lacelle

**Process Sheet** 

Customer: CC-DAR01 Dart Aerospace Ltd.

Drawing Name: D1005

Job Number: 26375

Part Number: Z\_CUSTOM

Job Number:



Seq. #:

**Machine Or Operation:** 

Description:

6.0 QC5 INSPECT WORK TO CURRENT STEP





Comment: INSPECT WORK TO CURRENT STEP

7.0


PACKAGING 1

PACKAGING RESOURCE #1



Comment: PACKAGING RESOURCE #1

REPACKAGE PER PPP



8.0





**Comment: DOCUMENT** 

Job Completion



